Continued Airworthiness – Service Publications – Safety Alert

Zlin Aviation S.R.O.

2. Kvetna 685763 61 NapajedlaCzech Republic

Safety Alert	Nº02	06 September 2007

MANDATORY

• Airplanes affected:

all Savage Aircrafts and models equipped with glass fuel filter

Subject:

Installation of fuel filter with safety wire.

• Reason:

Vibration can unscrew the fuel filter.

- Compliance: Issue date of SA
- Material required: 0,8 mm steel cable.

• Accomplishment:

- 1. dismount fuel filter (pic1) as show in "Savage maintenance manual"
- 2. check correct setting
- 3. make safety wire (pic2)
- 4. install fuel filter

Picture 1:



Picture 2:

